



# SERVICE INFORMATION

Techn. Customer Service  
VKT 20

Gi/Wi/Ha

Motorcycles R 50, 60, 69 S  
Group: Electrical System

München, Oct. 12, 1967  
Nr. 2/67 (262) eng.

Re: Burnt out ignition cable adapters

Dear Sirs,

If the ignition cable adapter is placed on the cylinder during idling speed adjustments, it becomes grounded and the resulting sparks might burn the adapter insulation partly.

When executing these operations, we recommend to mount a used adapter on the cable or to use a connector.

Very truly yours,

BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft

i.V.

i.V.

Delleske

Scholz

Kenntnis genommen — Pris connaissance — Noted — Tomado nota — Preso conoscenza				Ablage — Archives — File — Archivio			
Betriebsleitung Direction	Werkstatt Atelier	KD-Annahme Réception	Gewähr.-Sachb.	E-Teildienst	Betriebsleitung	Werkstatt	