



Service-Information

Cust.Serv.-Techn.Office VKT	e/wi/be	Motorcycles R50/R60/R69S/R27 Group: Springs and shock abs.	München, 7. 10. 65 Nr. 2/65 (224) en.
--------------------------------	---------	---	--

Re: Seal rings on the front wheel swing arm bearing

Dear Sirs,

The hitherto installed seal rings, Part No. 20 00 331, have in some cases been pushed away from their seat and pressed out of the swing when lubricating at high pressures.

New seal rings with a metal capsule are installed as standard equipment, by which measure a pressing-out is avoided.

The new seal rings are installed from the following frame numbers:

639 796	(R 50)
627 - 6	(R 60)
679 497	(R 69 S)
383 866	(R 27)

The Part Number remains unchanged.

Very truly yours,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.V.


Makowitzki

Delleske