

# SERVICE INFORMATION

|                                   |                     |                                      |  |
|-----------------------------------|---------------------|--------------------------------------|--|
| Techn. Customer Service<br>VKT 20 | Service<br>Gi/Wi/Ha | Motorcycles 2-cyl.<br>Group: Gearbox | München, Oct. 16, 1966<br>Nr. 1/67 (242) en. |
|-----------------------------------|---------------------|--------------------------------------|--|

Supplement 2

Re: Hex. nut for splined coupling cup



Dear Sirs,

As the hexagonal nut fixing the coupling cup to the cardan shaft is produced of a new material, its part number has been changed

from 07 11 9 921 636  
to 07 11 9 921 635.

The torque for this nut is 159 + 14.5 ft.lbs.

Very truly yours,  
BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft  
i.V. i.V.

  
  
Delleske Scholz

Kenntnis genommen — Pris connaissance — Noted — Tomado nota — Preso conoscenza      Ablage — Archives — File — Archivo

|  |  |  |   |  |   |  |
|--|--|--|---|--|---|--|
| Betriebsleitung<br>Direction<br>Management<br>Dirección<br>Direzione | Werkstatt<br>Atelier<br>Workshop<br>Taller<br>Officina | KD-Annahme<br>Réception clientèle<br>Cust. reception<br>Recepción clientela<br>Recepcion clienti | Gewährl. Sachb.<br>Inspecteur garantie<br>Warranty inspector<br>Inspector garantía<br>Inspector garanti | F-Teildienst<br>Service pièces détachées<br>Spare parts service<br>Servicio de recambios | Betriebsleitung<br>Direction<br>Management<br>Dirección | Werkstatt<br>Atelier<br>Workshop<br>Taller |
|--|--|--|---|--|---|--|