

# SERVICE INFORMATION

Techn. Customer Service  
VKT 20 Gi/wi-wi

Motorcycles with 2 cylind.  
Group: Engine

München, December 67  
No. 11/67 (264) eng

Re.: Wet air filter in engine housing

Dear Sirs,

As a result of many tests it has been proved that an additional cooling of the dynamo and the magneto ignition system by means of circulating cooling air is no longer necessary.

For this reason the channel for the air-conducting in the gear-box has been closed and the air filter in the engine housing is being superseded on the following models:

R 50	from frame No.	646 486 onwards
R 60	from frame No.	1 815 075 onwards
R 69 S	from frame No.	663 957 onwards.

By this modification the following parts are eliminated:


Air filter	Ordering no.	11 15 0 043 140
Clamping spring	ordering no.	11 15 0 043 136
Gasket A 48 x 55	ordering no.	07 11 9 963 493
Hex. screw M 6 x 10	ordering no.	07 11 9 913 425

Very truly yours

BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft

i.V.

i.V.

  
(Delleske)

  
(Scholz)