



Service-Information

Cust.Serv.-Techn.Office
VKT e/wi/be

Motorcycles R50/R50S/R5113;

München, le 7-10-65
N° 4/65 (223) engl.

*We didn't send this one to our dealers
so that they won't get confused.*

Re: Rocker Push rod

*We don't know what these gaskets look
like but have now ordered a few.*

Belint

Dear Sirs,

In order to ensure a sufficient adjustment range on the valve setting screw also on such motorcycles on which the thick cylinder base gasket (00 10 163) is fitted for a decrease of the compression ratio, the push rod has been lengthened from

hitherto 242 - 1.5 mm
to 243.5 - 1.5 mm.

The Part Number remains unchanged.

Very truly yours,
BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.V.

Makowitzki

Delleske