



SERVICE INFORMATION

Technical Customer Service
VKT 20 Gi/wi-ba

Two-cyl. motorcycles
Group: Transmission

München, June 15, 67
No. 1/67 (242) en.

Supplement 1

Re: Wrench socket 494/3 for tightening of the round nut
on gearbox output shaft

Dear Sirs,

Owing to the enlargement of the round nut, from M 14 to M 16, new Part No. 10 30 122, it was necessary to modify the wrench socket, too - new ordering number 494/3.

The new wrench socket possesses an inner square which may receive torque wrench as well as a square head with sliding handle. The inner diameter of the wrench socket has been increased, its quality of material improved.

The new wrench socket is also usable for the old round nut M 14, Part No. 10 30 120.

Very truly yours,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft

ppa.

i.V.

Makowitzki

Delleske

Kenntnis genommen /		Pris connaissance /		Noted /		Tomado nota /		Preso conoscenza	
Betriebsleitung Direction Management	Werkstatt Atelier Workshop	KD-Annahme Réception clientèle Cust. reception	Gewährl.-Sachb. Inspecteur garantie Warranty inspector	E-Teildienst Service pièces détachées Spare parts service	Ablage Archives File	Betriebsleitung Direction	Werkstatt Atelier		